

## Summary of I-5 Sign Replacement Locations & Associated Traffic Control\*

Highway	Direction	Mile Post	Approximate Location	Traffic Control / Closure / Detour Summary
I-405	NB	3.19	Fremont NB - west end. First sign truss NB on bridge, incl Kerby Ave Exit Only sign	US30 and NW Glisan on-ramps to I-405 NB closed. US30 traffic detoured to I-405 SB. Limited lane closures to facilitate work.
I-405	NB	3.30	Fremont NB - east end. Approaching I-84 exit lanes. New sign to be installed on the LEFT (in line with the exit).	US30 and NW Glisan on-ramps to I-405 NB closed. US30 traffic detoured to I-405 SB. Limited lane closures to facilitate work.
I-405	NB	3.40	Fremont NB - east end. Approaching splits for I-5 NB, I-5 SB and Kerby Ave.	US30 and NW Glisan on-ramps to I-405 NB closed. US30 traffic detoured to I-405 SB. Limited lane closures to facilitate work.
I-405	NB	3.63	Fremont NB - east end at off ramp to I-84.	Ramp closed to I-5 South / I-84 / US30 / The Dalles. US30 to I-405NB ramp closed. Traffic from US30, US26 and downtown I-405 on-ramps to use I-405 SB for I-84 access. Kerby Ave exit ramp closed (except for emergency vehicles). Limited lane closures to facilitate work.
I-405	NB	3.7	Fremont NB - east end at off ramp to Kerby	Kerby Ave exit ramp closed (except for emergency vehicles). Limited lane closures on I-405 NB.
I-5	NB	298.9	Exit 298 / Corbett Ave.	Exit 298 / Corbett Ave. closed. Limited lane closures to facilitate work.



### Summary of I-5 Sign Replacement Locations & Associated Traffic Control\*

I-5	NB	300.3	Marquam Bridge NB - just past the I-5/I-405 merge, Exit 300 sign	Full northbound closure of I-5 NB on the Marquam Bridge (upper deck). Traffic from I-5 NB, US26 and City Center detoured to I-405 NB. Limited lane closures.
I-5	NB	300.5	Marquam Bridge NB, before Exit 300 (OMSI/I-84)	Limited lane closures.
I-5	NB	300.69	Marquam NB, at Exit 300 (OMSI)	Limited lane closures.
I-5	NB	302.29	NE Weidler overpass	Limited lane closures.
I-5	NB	302.53	N Flint overpass	I-5 NB on-ramp from NE Broadway / N. Williams closed. Limited lane closures.
I-5	NB	304.68	N. Ainsworth overpass	Limited lane closures.
I-5	NB	304.93	N. Rosa Parks overpass	Limited lane closures.
I-5	NB	305.12	Just south of N. Pedestrian bridge, Lombard Exit 305A	I-5 NB on-ramp from N. Rosa Parks Way closed. Limited lane closures.
I-5	NB	305.28	Exit 305A	Exit 305A / N. Lombard St. closed. Limited lane closures.
I-5	NB	305.42	At Lombard overpass	Exit 305A / N. Lombard St. closed. Limited lane closures.



### Summary of I-5 Sign Replacement Locations & Associated Traffic Control\*

I-5	Both	299.21	Exit 299A / RIB & Macadam Ave	Exit 299A / Ross Island Bridge /US26, Macadam / OR43 closed. Detour: I-5 NB to I-405, Exit 1A Downtown, SB 99W/Naito to US26 or OR43.
I-5	Both	301.13	North of Morrison Bridge	Full closure of I-5 NB and SB. <u>NORTHBOUND detour:</u> I-405NB. <u>SOUTHBOUND detour:</u> I-5 traffic to I-405 SB. I-84 traffic to I-5 NB to I-405 SB.
I-5	Both	298.76	Exit 298 / Corbett Ave.	Exit 298 / Corbett Ave. closed. Limited lane closures in both directions to facilitate work.
I-5	Both	301.86	Exit 301 SB / I-84	NORTHBOUND: Full closure from Marquam Bridge to Fremont Bridge. <u>Detour:</u> I-405NB.
				SOUTHBOUND: Exit 301 to I-84/ Water Ave. closed. <u>Detour:</u> Exit 300B to Belmont-Grand / 99E to I-84 on-ramp. Limited lane closures.
I-5	Both	302.1	Adjacent to Rose Quarter, start of exit only lane for Exit 301	NORTHBOUND: Exit 302A / Broadway-Weidler, Moda Center closed. Limited lane closures. SOUTHBOUND: I-5 SB on-ramp from NE Wheeler Ave closed. Limited lane closures.



### Summary of I-5 Sign Replacement Locations & Associated Traffic Control\*

I-5	Both	302.7	At location of existing cantilever & sign #112 for Exit 302C / Greeley / Swan Island.	Full closure of I-5 NB and SB for truss and sign installation. Limited lane closures for drilled shaft installation.  <u>NORTHBOUND detour:</u> I-405 NB. Northbound traffic from I-84 detoured to I-405 NB.  <u>SOUTHBOUND detour:</u> I-5 traffic to I-405 SB.
I-5	Both	302.8	Exit 302B for I-405/Fremont Bridge	<u>NORTHBOUND:</u> Full closure from Marquam Bridge to Fremont Bridge. <u>Detour:</u> I-405NB.  <u>SOUTHBOUND:</u> Exit 301 to I-84/ Water Ave. closed. Detour: Exit 300B to Belmont-Grand / 99E to I-84 on-ramp. Limited lane closures.
I-5	Both	303.41	Exit 303 NB (Killingsworth/Swan Island) / Exit 302B SB (I-405 / Fremont)	<u>NORTHBOUND:</u> Full closure from Marquam Bridge to Fremont Bridge for some sign replacement. <u>Detour:</u> I-405NB. Also limited lane closures for some sign replacement.  <u>SOUTHBOUND:</u> Full closure with I-405 SB detour for some sign placement. Also, Exit 302B / I-405 SB closure with detour to I-405 NB. Also limited lane closures.



### Summary of I-5 Sign Replacement Locations & Associated Traffic Control\*

I-5	Both	304.18	N. Alberta overpass	Limited lane closures only.
I-405	SB	3.07	Fremont SB - west end. At I-405 / US30 split.	Limited lane closures. Possible closure of I-405 SB. Detour: I-5 SB to I-405 NB
I-405	SB	3.42	Fremont SB - east end at beginning of arch.	Limited lane closures.
I-5	SB	300.23	Marquam SB at I-405/I-5 split	Two separate closures will be needed: <u>I-5 SB closed.</u> Detour I-5 traffic to I-405 SB, I-84 traffic to I-5 NB to I-405SB. Limited lane closures. <u>I-5 SB to I-405 NB closed.</u> Detour to I-5 NB to I-405 SB. Limited lane closures.
I-5	SB	300.38	Marquam SB - before I-405/I-5 split	Limited lane closures.



### Summary of I-5 Sign Replacement Locations & Associated Traffic Control\*

I-5	SB	300.72	Marquam SB - east side, south of Hawthorne Bridge	Limited lane closures.
I-5	SB	301.42	Morrison Bridge / OMSI exit	I-5 SB and I-84 to I-5 SB closed. Detour: I-5 SB to I-405 SB and I-84 to I-5 NB to I-405 SB.
I-5	SB	301.64	Exit 300B SB	Limited lane closures.
I-5	SB	301.95	Just south of existing Exit 301 cantilever	Limited lane closures.
I-5	SB	302.35	NE Broadway overpass	Limited lane closures.
I-5	SB	302.59	Exit 302A / Moda Center	Limited lane closures.
I-5	SB	303.62	Failing Street Ped Bridge	Limited lane closures.
I-5	SB	303.78	Just south of Skidmore overpass / Going St on-ramp. Lined up with N. Mason.	Exit 302B to I-405 SB / US30 / Beaverton / St. Helens closed. Limited lane closures. Detour: I-5 SB to I-405 NB / US26 / City Center / Beaverton
I-5	SB	304.44	Just north of Killingsworth, Exit 303	Exit 303 / Alberta Street, Swan Island closed. Limited lane closures. Detour: Exit 304 / Rosa Parks Way to Greeley Ave, south to Going St.



### Summary of I-5 Sign Replacement Locations & Associated Traffic Control\*

I-5	SB	305.06	Exit 304	Exit 304 / Rosa Parks Way closed. Limited lane closures. Detour: Exit 303 / Alberta Street, Swan Island
I-5	SB	305.23	Just north of N. Pedestrian bridge, south of Lombard on-ramp	EB Lombard St. on-ramp to I-5 SB closed. Limited lane closures. Detour: Lombard EB to NE Martin Luther King Jr. Blvd SB to N. Rosa Parks Way.
I-5	SB	305.44	At Lombard overpass	WB Lombard St. on-ramp to I-5 SB closed. Limited lane closures. Detour: NE Martin Luther King Jr. Blvd SB to NE Rosa Parks Way.

## I-5 Ramps To Be Paved (from North to South) \*

Ramp Location
I-405 to I-5 SB
I-5 NB to I-405
I-5 NB to Marquam Bridge / Exit 299B
I-5 / I-405 NB to Naito Parkway
Marquam Bridge SB to Hood Ave / OR43 / Exit 299A
Marquam Ramp to I-5 SB
Hood Ave to I-5 SB
I-5 NB to Macadam Ave / Exit 299A
I-5 NB to Terwilliger / Exit 297
I-5 NB to Taylors Ferry Rd and SW 35th Ave / Exit 295
SW Huber St to I-5 NB
I-5 SB to Taylors Ferry Rd / Exit 295
Capitol Hwy to I-5 SB